

NASA Technical Memorandum 89825

Design, Development, and Test of Shuttle/ Centaur G-Prime Cryogenic Tankage Thermal Protection Systems

Richard H. Knoll
Lewis Research Center
Cleveland, Ohio

and

Peter N. MacNeil and James E. England
General Dynamics
Space Systems Division
San Diego, California

(NASA-TM-89825) DESIGN, DEVELOPMENT AND
TEST OF SHUTTLE/CENTAUR G-PRIME CRYOGENIC
TANKAGE THERMAL PROTECTION SYSTEMS (NASA)
42 p Avail: N115 EC A03/MF AC1 CSCL 22B

N87-23685

H1/18 Unclassified
0077496

May 1987



Trade names or manufacturers' names are used in this report for identification only. This usage does not constitute an official endorsement, either expressed or implied, by the National Aeronautics and Space Administration.

DESIGN, DEVELOPMENT, AND TEST OF SHUTTLE/CENTAUR G-PRIME CRYOGENIC
TANKAGE THERMAL PROTECTION SYSTEMS*

Richard H. Knoll
National Aeronautics and Space Administration
Lewis Research Center
Cleveland, Ohio 44135

and

Peter N. MacNeill and James E. England
General Dynamics
Space Systems Division
San Diego, California

SUMMARY

The thermal protection systems for the shuttle/Centaur would have had to provide fail-safe thermal protection during prelaunch, launch ascent, and on-orbit operations as well as during potential abort, where the shuttle and Centaur would return to Earth. The thermal protection systems selected used a helium-purged polyimide foam beneath three radiation shields for the liquid-hydrogen tank and radiation shields only for the liquid-oxygen tank (three shields on the tank sidewall and four on the aft bulkhead). A double-walled vacuum bulkhead separated the two tanks. The liquid-hydrogen tank had one 0.75-in.-thick layer of foam on the forward bulkhead and two layers on the larger-area sidewall. Full-scale tests of the flight vehicle in a simulated shuttle cargo bay that was purged with gaseous nitrogen gave total prelaunch heating rates of 88 500 Btu/hr and 44 000 Btu/hr for the liquid-hydrogen and -oxygen tanks, respectively. Calorimeter tests on a representative sample of the liquid-hydrogen-tank sidewall thermal protection system indicated that the measured unit heating rate would rapidly decrease from the prelaunch rate of ~100 Btu/hr ft² to a desired rate of <1.3 Btu/hr ft² once on-orbit.

INTRODUCTION

The shuttle/Centaur G-prime vehicle, using liquid hydrogen and liquid oxygen as propellants, was designed for use in the Space Transportation System (STS) and afforded a means of significantly increasing the payload capability of the STS (ref. 1). Although the shuttle/Centaur project has been terminated, the design, development, and test history of the cryogenic tankage thermal protection systems used for the vehicle are reviewed to possibly benefit future programs requiring the transfer of cryogenics to Earth orbit.

The thermal protection systems for the Centaur G-prime liquid-hydrogen and -oxygen tanks were unique in that they would have had to provide thermal protection during prelaunch, launch-ascent, and on-orbit operations as well as

*A shorter version of this report was presented at the 22nd Thermophysics Conference sponsored by the American Institute of Aeronautics and Astronautics, Honolulu, Hawaii, June 8-10, 1987 (AIAA-87-1557).

during abort operations, where the shuttle and its cargo would return to designated landing sites. Other cryogenic stage thermal protection systems such as those for the shuttle main tank, the Saturn, and the Centaur D-1A (ref. 2) provide protection primarily during prelaunch and aerodynamic boost. The Centaur D-1T (ref. 3), used as a second stage on the Titan, also had to provide thermal protection for an extended time on-orbit, but none of the expendable vehicles had a requirement to return to Earth. In addition to affording thermal protection during descent and landing (and after landing), it was imperative that the Centaur G-prime thermal protection systems not be hazardous to the shuttle or its crew.

This report describes (1) the basic design of the shuttle/Centaur G-prime thermal protection systems, (2) various small-scale and full-scale developmental tests, (3) shuttle-related developmental problems encountered and their solutions, and (4) the full-scale performance of the flight system in a simulated shuttle cargo bay during prelaunch operations. Emphasis is placed on the liquid-hydrogen-tank insulation system as it had to meet the design criteria imposed on all shuttle/Centaur thermal protection systems plus had the additional requirement, because of the lower temperature of the liquid-hydrogen tanks, of precluding formation of liquid air or liquid nitrogen on any of its surfaces.

SYSTEM DESIGN REQUIREMENTS

Thermal Requirements for Mission

The shuttle/Centaur G-prime vehicle (ref. 1) was originally designed to propel the Galileo and Ulysses spacecraft from low-Earth orbit to their respective destinations of Jupiter and a polar orbit about the Sun (via Jupiter). The G-prime vehicle and its payloads were to be inserted into low Earth orbit by the STS. Once in orbit the orbiter cargo bay doors were to open to allow the Centaur G-prime to be rotated by its integrated support structure for eventual separation from the orbiter (fig. 1). Nominal mission time was 6 hr from STS launch to separation from the orbiter. An additional 3 hr was allowed for deployment delay, giving a total of 9 hr. During this 9 hr the thermal environment imposed on the vehicle would vary from a room-temperature, gaseous-nitrogen-purged environment at launch to the near vacuum of space, with a varying radiant heat flux once on-orbit. Additionally in case of an abort the orbiter cargo bay would have had to be refilled with atmospheric air during its descent to Earth.

Figure 2 gives additional details of the Centaur G-prime and the Centaur integrated support structure (CISS) used for interfacing with the shuttle. The vehicle is supported by a cylindrical deployment adapter on its aft end and by a three-point attachment system on its forward end. The CISS would have provided all the necessary fluid and electrical interfaces for the vehicle plus the hardware required for deployment.

The basic vehicle, before installation of the cryogenic tankage thermal protection systems and other flight hardware, is shown in figure 3. The vehicle had the following key thermal features: (1) the highly conductive aluminum conical forward adapter (where most of the avionics and other equipment was mounted) was supported off the liquid-hydrogen tank forward ring by a low-conducting, 25-in.-high composite adapter; (2) the liquid-hydrogen and -oxygen

tanks were separated by a double-walled vacuum bulkhead that contained a cryo-pumped insulation system to limit gaseous conduction; and (3) a low-conducting composite adapter was also used between the aft end of the liquid-oxygen tank and the warmer aluminum deployment adapter of the CISS.

In order to accomplish the intended missions, in the rather severe and varying environment discussed previously, the following thermal criteria were imposed on the cryogenic thermal protection systems:

(1) The system shall be designed to prevent liquefaction of air or the cargo bay gaseous-nitrogen purge gas on any external surface of the insulation system.

(2) The prelaunch heating rates of the liquid-hydrogen and -oxygen tanks shall be less than 103 000 and 40 000 Btu/hr, respectively, while in the gaseous-nitrogen-purged cargo bay.

(3) The maximum on-orbit heating rates through the liquid-hydrogen-tank forward bulkhead and sidewall insulation system shall not exceed 1690 and 1570 Btu/hr, respectively.

(4) The maximum on-orbit heating rates through the liquid-oxygen-tank sidewall and aft bulkhead shall not exceed 175 and 180 Btu/hr, respectively.

With these requirements imposed on the cryogenic tankage thermal protection systems, along with other restrictions on penetration heat leaks and the heat leak through the double-walled vacuum bulkhead, the Centaur G-prime could perform its intended missions.

Requirements Imposed by Shuttle Cargo Bay

As a payload in the STS the Centaur G-prime had to meet the safety requirements specified in references 4 and 5 and had to withstand the STS-induced environments described in reference 6. Some of the more important safety criteria influencing the thermal protection system design were as follows:

(1) Materials must be noncombustible or self-extinguishing in the upward flame propagation test of reference 7 (less than 6 in. burned in a 12-in.-long sample).

(2) The insulation system shall be designed to an ultimate safety factor of 1.4 or more and shall be capable of withstanding limit loads without loss of function and ultimate loads without failure.

(3) All systems shall be two-failure tolerant against catastrophic hazards.

(4) Any material exposed to gaseous or liquid oxygen must pass the impact sensitivity tests of reference 7.

(5) All hardware with metalized surfaces shall be electrically bonded per MIL-B-5087. Cargo bay hardware with volume resistivities greater than 10^9 ohms-cm shall not accumulate an electrical charge.

The STS-induced structural loads that had to be considered in the design of the thermal protection systems were launch and emergency landing loads, mechanical loads due to structure-borne or airborne (i.e., acoustical) excitations, loads due to rapid pressure changes in the cargo bay during ascent and abort descent, and localized loads on the insulation system due to flow impingement near the cargo bay vent ports.

Finally all materials used in the cargo bay had to meet strict outgassing and cleanliness requirements.

SYSTEM DESIGN

Basic Design Concept

The basic cryogenic thermal protection systems selected for the shuttle/Centaur G-prime vehicle are depicted in figure 4. The liquid-hydrogen tank was insulated with a combination of helium-purged, open-cell polyimide foam and radiation shields; the liquid-oxygen tank used radiation shields only.

The helium-purged insulation system on the liquid-hydrogen tank was required to prevent liquefaction of the cargo bay gaseous-nitrogen purge during prelaunch and to prevent liquefaction of air during abort operations, when the cargo bay would be refilled with air during shuttle descent. (The gaseous-helium purge would be terminated at lift-off but reinitiated if an abort occurred.) The helium purge was contained by the forward adapter purge diaphragm (fig. 4), the forward adapter itself, the innermost sidewall radiation shield, which was external to the foam and acted as a sealed membrane, and the purge plenum, which sealed the system on the aft end of the liquid-hydrogen tank. The foam insulation (1.5 in. on the tank sidewall and 0.75 in. on the forward bulkhead) was used to achieve sufficient thermal resistance to meet the ground-hold heating criteria and to ensure that all the radiation shield temperatures exceeded the liquefaction temperatures of the surrounding gases during operation within the atmosphere. The radiation shields themselves afforded very little thermal protection during ground-hold operations but would provide nearly all the thermal protection once the shields were evacuated on-orbit. Three shields on both the liquid-hydrogen-tank forward bulkhead and sidewall were determined to be sufficient to meet mission requirements.

The liquid-oxygen tank used radiation shields only and required no purge since there was no danger of liquefying the gaseous-nitrogen purge or air on the warmer liquid-oxygen-tank surface. Because of the heat capacity and relatively small surface area of the liquid-oxygen tank, little or no thermal protection was needed for the ground-hold phase. The shields were used primarily to afford thermal protection on-orbit. Three shields were used on the tank sidewall and four on the aft bulkhead. The inner and outer shields on the aft bulkhead (fig. 5) were edge vented rather than broadside vented. From the standpoint of gas evacuation on-orbit, it would be better to have all shields broadside vented. The edge venting of the inner and outer shields was primarily used to contain and funnel the colder gaseous nitrogen to areas where temperature-sensitive components would not be affected during prelaunch.

Figure 5 also depicts some of the other radiation shield systems used on the aft-end components. The list is not complete but illustrates the shape, size, and variety of shield systems required to meet the mission objectives.

The number of shields used on the various components varied with the thermal requirements of each component, but in general the liquid-oxygen tank did not require special purge systems as did the liquid-hydrogen tank.

The general operation of the purge system for the liquid-hydrogen-tank thermal protection system is depicted in figure 6. A controlled flow of helium from the Centaur integrated support structure (CISS) would enter the helium-purged volume, discussed previously, through the forward adapter. The helium supply system from the CISS (not shown) had two redundant flow control branches that were controlled by the three differential pressure (ΔP) transducers located within the forward adapter purge volume. These ΔP transducers measured the differential pressure between the enclosed volume of the forward adapter and the external environment surrounding the Centaur (i.e., the STS cargo bay). The system was single-failure tolerant against failure of the ΔP control transducers and single-failure tolerant mechanically to prevent overpressurization during an abort return. Software control via the ΔP set points allowed the purge volume differential pressure to be adjusted for various phases of prelaunch and postlaunch activities.

The helium purge would begin roughly 1 hr before the cryogenic propellants were loaded. Prior to this time gaseous nitrogen would be maintained in the purge volume to preclude any damage to the shield surfaces from moisture condensation. At helium purge initiation the insulation blanket ΔP limits were set high enough to allow the ΔP within the purge volume to exceed that necessary to open the relief valves located in the purge plenum on the aft end of the liquid-hydrogen tank. These relief valves opened at a nominal 0.4 psid. Once the valves were opened, the heavier gaseous nitrogen would be forced out by the lighter helium entering the forward bulkhead area. Figure 6 schematically shows the purge flow through one of the relief valves during the gaseous-nitrogen removal cycle. This flow and blanket ΔP would be maintained for at least 1 hr to ensure that most of the condensable gases were purged from the system. After 1 hr the blanket ΔP control limits would be reset (via software) to maintain the nominal ΔP between 0.1 and 0.3 psid, thus closing the relief valves. At this point the helium purge supply would be governed by the leakage rate of the insulation blanket. The liquid-oxygen and -hydrogen tanks would then be loaded (~9 hr before launch).

These ΔP limits would be generally maintained until just before launch, when the limits would be lowered preparatory to venting the cargo bay at lift-off. This was necessary since the cargo bay itself is slightly pressurized (0.5 to 0.7 psid) by its gaseous-nitrogen purge. A similar adjustment in blanket pressure would also occur earlier when the cargo bay pressure would be adjusted for hazardous gas checks. At launch a vent door (not shown) in the forward adapter would be opened, and the pressure within the contained purge volume would then closely follow that of the cargo bay during ascent. In an abort a second vent door would reseal the forward adapter, and the helium purge would be reinitiated.

Design of Liquid-Hydrogen-Tank Insulation System

As discussed previously the radiation shields on the liquid-hydrogen tank were representative of most of the shields used for the Centaur G-prime thermal protection systems. Because of the additional need to prevent liquefaction of the gases surrounding the liquid-hydrogen tank, the resulting insulation system

was more complex and as a result was the focal point for most of the developmental testing. For this reason only the liquid-hydrogen-tank insulation system is addressed in more detail for the remainder of this report.

Material selection. - The insulation materials selected for the liquid-hydrogen tank are shown in figure 7. The purge diaphragm on the forward end of the vehicle consisted of two Kevlar-cloth-reinforced shields separated by an embossed Kapton shield. The high-strength reinforced shields were required to withstand a purge system design ΔP of 0.5 psid. These shields are actually laminates with the high-strength Kevlar cloth sandwiched between two layers of Kapton. All shield surfaces had a vapor-deposited layer of aluminum (VDA) applied to achieve emittances of 0.05 or less. The embossed Kapton was used for the middle shield to save weight (unit weights are given in table I). Both of the outer two shields were broadside vented so that they could be rapidly evacuated during ascent to eliminate most of the gaseous conduction heat transfer. The nonvented inner shield provided the required seal for the helium purge.

The insulation system for the forward bulkhead consisted of a 0.75-in.-thick layer of open-cell polyimide foam covered by three radiation shields. The outermost shield is a laminate of Nomex scrim sandwiched between two layers of Kapton. This material was selected for its low weight and rip-resistant features. The higher strength material used on the purge diaphragm was not required here since the forward bulkhead insulation was completely contained within the helium-purged volume and therefore was not exposed to any differential pressures. The center shield was embossed Kapton and the innermost shield was a flat Kapton sheet (again for weight savings), and all three shields had a VDA coating on all exposed surfaces. Both of the outer two shields were broadside vented; the inner shield was edge vented. Edge venting on the inner layer was selected to minimize the amount of helium between the shields during ascent venting of the forward bulkhead area. The foam insulation next to the tank wall contained a typical twin-pin fastener used to attach adjacent foam panels. A layer of Tedlar tape was applied over the seam before pin installation to help minimize direct convection paths between the shields and the tank surface.

The materials selected for the sidewall shield system consisted of two layers of polyimide foam (each 0.75-in.-thick) covered by three radiation shields. The shields were identical to those used on the purge diaphragm except for the outermost laminate material used on the outboard shield. Instead of Kapton with an external VDA coating, a 0.5-mil-thick layer of Teflon with an internal VDA coating was used to achieve a relatively low ratio of solar absorptance to thermal emittance α/ϵ . This low ratio was required to help minimize heating from the Sun and the Earth's albedo while on-orbit. Material specifications for all outboard radiation shield surfaces required that the solar absorptance be less than or equal to 0.14 and the thermal emittance be greater than or equal to 0.4 to give an α/ϵ ratio of less than 0.35.

The structural property requirements of the sidewall shield material were primarily dictated by the radial hoop stress created by the design differential pressure of 0.5 psid used for the helium purge system. For the 87-in.-radius sidewall shield, a material tensile strength of 43.5 lb/in. was required. With an ultimate factor of safety of 1.4 the shield material had to have a tensile strength exceeding 61 lb/in. (1.4×43.5). The material specifications were conservatively established at a minimum tensile strength of 100 lb/in. The

material eventually selected - the Kevlar-reinforced shields - had a measured tensile strength of 239 lb/in. in the undamaged state and 191 lb/in. with the material severely creased.

Finally the particular materials selected met the flammability and out-gassing requirements of the shuttle cargo bay and in many cases were the same general materials used extensively in the cargo bay (e.g., aluminized Kapton).

Design details. - The general method of attachment and construction of the forward adapter purge diaphragm is shown in figure 8. The diaphragm was constructed from gore sectors sewn at their adjoining seams. Each gore sector contained three radiation shields. The sewn joint seam had aluminized (VDA) tape applied both outboard and inboard. The inboard tape had a thermal plastic adhesive to help ensure an adequate seal. A circular shield section was applied similarly in the center of the diaphragm to close out the shield. At the outer edges of the diaphragm a Kevlar strip was sewn to the shields to provide a rigid edge member for attachment to the forward adapter. The method of attachment, shown in view D, sandwiches the Kevlar edge member between the adapter and a retainer ring bolted around the periphery of the diaphragm. A silicone sealant was applied to the edge member and the forward adapter to ensure a proper seal. An installed diaphragm is shown in figure 9.

Details of the insulation system used for the forward bulkhead area are given in figure 10. The cross section of the forward adapter shows the corrugated composite stub adapter joining the aft ring of the aluminum conical adapter to the forward ring of the liquid-hydrogen tank. A 12-in. strip of polyimide foam, which overlapped the tank sidewall foam, was bonded to the apexes of the corrugation to preclude localized chilling of the overlying radiation shield. Foam was bonded to an outside corrugation of the adapter wherever a seam was required in the 12-in. foam strip (six places). Polyimide foam was also bonded to all the inside corrugations to help reduce convective heat exchange inside the adapter from the tank surface just forward of the tank ring. The 0.75-in.-thick polyimide foam layer used on the forward bulkhead surface penetrated as far as practical into this crevice. It was held in place by the radiation shields, which were attached with Velcro to the inner surface of the composite adapter. The twin-pin fasteners that hold the adjacent gore-shaped foam panels together, intermittently penetrated the radiation shields to secure the two systems together. Figure 11 shows the foam panels being assembled for the full-scale test vehicle, which was representative of the flight articles. As shown, the foam seams, containing the twin-pin fasteners, were taped to minimize direct convective currents between the liquid-hydrogen-tank surface and the overlying shields. The hole in the foam at the top of the insulation panels was for an access door to the liquid-hydrogen tank. At final assembly a foam panel and a radiation shield cover were applied over the door.

The three-layer radiation shield system used on the forward bulkhead was laid up and attached to the underlying polyimide foam (shown in fig. 11) before it was applied to the liquid-hydrogen tank. The inner two shields were each fabricated by taping 16 adjacent gore sectors together on the foam-covered layup tool. The outermost, Nomex-scrim reinforced shield, was made up of four quadrant-sized pieces that were intermittently attached along their edges by twin-pin fasteners penetrating the entire assembly. Each quadrant was formed by sewing together four gore-shaped panels as shown in figure 12. The sewn seams used a simple stitch joint because the shield system did not have to withstand pressure forces as did the purge diaphragm. The Velcro pattern near

the center of the shield was for attachment of the forward door shield. Not shown, for clarity, are the other two shield quadrants and the various penetrations for tank vents, instrumentation, etc. The entire insulation system on the forward bulkhead, including the foam, the shield, the fasteners, etc., weighed 22.5 lb, or about 0.085 lb/ft².

Details of the liquid-hydrogen-tank sidewall insulation system are shown in figure 13. As discussed previously two 0.75-in.-thick layers of polyimide foam with three overlying radiation shields provided the necessary thermal protection for the liquid-hydrogen-tank sidewall. Each layer of foam was composed of several panels, each containing a cylindrical sector and a conical sector and running from the forward tank ring to the aft end of the conical section of the liquid-hydrogen tank. The cylindrical and conical sectors were bonded where they met. The seams between adjacent panels (running fore and aft) of the inner layer were offset from those of the outer layer to minimize direct convective currents between the tank surface and the overlying shields. The foam panels were held at the fore and aft ends by support channels attached to the forward tank ring and by channels attached to tank brackets at the aft end of the tank's conical portion. The foam panels had Kevlar channels bonded to their edges fore and aft to reinforce the support pins that held the panels within the brackets. Figure 14 shows the installation of one of the inner panels at the forward tank ring. Also shown is a twin-pin fastener penetrating the side of the panel, which again had bonded Kevlar strips to reinforce the foam panel. The aft brackets for foam panel attachment are shown in figure 15 along with the purge plenum, which transitioned the vacuum bulkhead between the liquid-oxygen and -hydrogen tanks. The aft end of the plenum was bolted to and sealed to a continuous circumferential ring on the forward end of the liquid-oxygen tank. (Also shown is one of the two purge relief valves discussed previously in the section "Basic Design Concept.") The entire inner surface of the plenum was lined with a 0.75-in.-thick layer of polyimide foam to maintain temperatures well above the condensation temperature of air or gaseous nitrogen.

Most major penetrations of the liquid-hydrogen-tank insulation system were made in one localized area (designated "the cableway") to minimize sealing problems for the helium purge system. The aft end of this area is shown in figure 16. All the required wire harnesses and fluid lines extended forward up the side of the liquid-hydrogen tank to the forward adapter. Foam insulation was installed both beneath and above these harnesses and fluid lines in the cableway area (outer layer is not shown). The brackets for attaching the sidewall foam panels are shown on both sides of the cableway. Once the sidewall foam panels were attached to these brackets, a strip of Tedlar tape was applied along the whole length of both seams to minimize convective flow from these direct butt joints. The engine feed line and tank fill/drain line, shown exposed, had insulated shroud enclosures that were sealed and purged with helium during prelaunch operations. Before these shrouds were installed, Tedlar tape was used to seal off all direct butt joints with the adjoining foam panels. An additional insulated-purged shroud also was installed over the lower end of the cableway with its uppermost surface running laterally between the two liquid-hydrogen line shrouds.

Details of the liquid-hydrogen-tank sidewall radiation shield construction are given in figure 17. The shield was assembled from 3 circumferential panels and 13 conical sectors. The maximum size of the panels was dictated by the available stock width of the radiation shield materials. Each panel contained

three radiation shields, as described previously, with the nonvented sealing shield located inboard. The radiation shields for each panel were temporarily held in place with aluminized Kapton tape before they were sewn for the final assembly. A typical sewn joint used to join adjacent panels is shown in view A-A. Two stitches are used to secure the joint and then a VDA-coated tape with a thermal plastic adhesive was applied to the inner surface, and a VDA-backed Teflon tape was applied to the outer surface. The tape used externally was selected because it approximately matched the α/ϵ ratio of the outer shield surface. A typical shield edge for mechanically attaching the shield to the vehicle is shown in view C-C. The shield was sewn to the thinner section of a reinforcing Kevlar strip and then taped as discussed previously. The thicker portion of the reinforcing strip was sandwiched between the desired sealing surface and a retaining ring held with bolts and sealed nutplates as shown in figure 13 (for attachment to the purge plenum). A sealant was used on the inboard surface of the reinforcing strip to complete the seal. The radiation shield system was sealed similarly at its forward end to the aluminum adapter ring (e.g., see fig. 10) and laterally along the port side of the area containing the fluid lines and electrical harnesses. Areas around the line penetrations, etc., were treated similarly. The completed sidewall insulation system (including the shields, the foam layers, the fasteners, the retainer rings, etc.) weighed 119.2 lb, or about 0.25 lb/ft².

The completed insulation system for the vehicle is shown in figure 18. There were many other insulated components on the vehicle, and they in general used three or four shields with the same materials and assembly techniques (i.e., sewn seams). Exceptions were as follows: (1) the liquid-oxygen sump contained 16 shield layers, and (2) the liquid-hydrogen fill/drain line, aft of the purged elbow at the tank, used a sealed foam under non-helium-purged radiation shields.

Finally the techniques used to electrically ground all the metallized (VDA) shield surfaces on the vehicle are shown in figures 19 and 20. The VDA surfaces of the radiation shields were grounded to the vehicle by using the techniques shown in figure 19. Specifications for assembling the shield system required that the resistance between any vehicle ground and any vehicle radiation shield be less than 100 ohms. The resistance across the ground wire attachment itself had to be less than 1 ohm.

As mentioned previously the outermost shields on the vehicle had a 0.5-mil-thick Teflon coating covering a VDA coating within the shield laminate. Because of the large surface area of the sidewall shields there was concern that this "hidden" VDA surface could act as one plate of a large capacitor if sufficient charge were to accumulate from whatever source. Although a charging mechanism was not present for the anticipated missions, the hidden VDA was grounded as a precautionary measure. The method finally selected for grounding the hidden VDA is shown in figure 20. A conductive ink was applied on all external shield edge surfaces. This served to electrically connect the hidden VDA with the exposed VDA on the underside of the shield (which was grounded to the vehicle by the techniques shown in fig. 19). Test tabs were also included on major shield surfaces to verify that the hidden VDA was grounded and to help monitor any degradation with time. Requirements specified that the resistance between the exposed VDA surface (grounded to the vehicle) and the hidden VDA surface be less than 50 000 ohms. This was more than adequate to preclude any electrostatic discharge since it provided a leakage path for any accumulated charges.

Predicted performance. - The predicted steady-state heat transfer rates into the insulated liquid-hydrogen tank are given in table II for prelaunch ground hold and for a representative on-orbit case for the Galileo mission. It is apparent that the forward bulkhead and sidewall are the predominant heat transfer contributors during ground hold, whereas the common vacuum bulkhead would be the major contributor once on-orbit. The surface areas of these major contributors are as follows: forward bulkhead¹ 216 ft²; sidewall, 483 ft²; and intermediate bulkhead, 129 ft².

The predicted transient performance of the forward bulkhead and sidewall insulation systems is shown in figure 21. Shortly after launch the expected heating rates drop by roughly a factor of 100 once the pressures within the insulation approach near-vacuum conditions. The radiation shield temperatures and heating rates then rise until the cargo bay doors are opened at 1 hr after launch. At this point the temperatures generally decrease in a cyclic fashion (due to day-night cycles) as steady-state conditions are approached. These predicted temperatures and heating rates are compared with those achieved during developmental testing in subsequent sections of the report.

DEVELOPMENTAL TESTING

In developing the Centaur G-prime thermal protection systems, many tests, varying from simple bench tests to full-scale system hardware tests, were performed. For convenience of discussion these tests are grouped into the following general categories (not necessarily in chronological order): (1) small-scale material tests; (2) calorimeter tests; (3) tests related to shuttle cargo bay safety requirements; (4) full-scale liquid-hydrogen-tank insulation system tests; and (5) flight vehicle ground-hold tests.

Small-Scale Material Tests

Polyimide foam tests. - The polyimide foam used for the liquid-hydrogen tank was an open-cell foam with a density of 0.60 lb/ft³. The tests performed on the foam and the test results are summarized as follows:

(1) Mechanical properties: The measured average ultimate tensile strength and modulus of elasticity at -320 °F were 17.6 and 140 psi, respectively.

(2) Thermal properties: The measured coefficient of thermal expansion was 4.4×10^{-5} in./in. °F between -121 and 3 °F.

(3) Air purgeout: The time required to reduce the air concentration to 10 percent with a helium purge from top to bottom along the longest dimension was 8.3 min for a sample 1 by 10.75 by 46.5 in.

(4) Particle generation during rapid depressurization: An insignificant number of particles were given off, and no cell breakage was detected after the open-cell polyimide foam was subjected to a launch-ascent pressure profile.

¹The actual surface area of the forward bulkhead is 266 ft². For convenience of thermal modeling a portion of this area was accounted for in the forward adapter calculation.

(5) Heat forming: The heat-forming cycle for the curvatures required for the Centaur G-prime tank was determined to be 15 min at 500 °F.

(6) Insulation compression due to rapid chilling of helium during liquid-hydrogen tanking: A 4.0-in.-diameter, 1.0-in.-thick cylindrical foam specimen was tested for compression and recovery at temperatures experienced during tanking. The equilibrated surface temperatures were -360 °F for the bottom and -150 °F for the top. The compression was 0.37 in., and the recovery was 100 percent in approximately 2 min.

In general the foam tested was ideal for the application intended and met all mission requirements.

Shield material tests. - The structural tests performed on the reinforced radiation shield materials and the sewn seams are summarized in table III. The fiberglass-cloth-based material was originally selected and used in the full-scale insulation tests discussed later in this report. The creased-strength data were acquired after several small creases were noticed as the shield was being assembled for the full-scale test vehicle. These data and results of the full-scale insulation system tests eventually led to changing the liquid-hydrogen-tank sidewall shield material to the Kevlar-based material, which has superior strength even in the creased state. As shown, the strength of the sewn seam joint samples also exceeded the 43.5-lb/in. design requirement.

The radiative surface properties of the shield materials were also determined, and representative results are given in table IV. The fiberglass data are for a fiberglass cloth that was strategically located on components exposed to exhaust plume heating from the vehicle's reaction control system. The materials used met all the requirements.

Calorimeter Tests

A series of tests were performed on a 9.5-in.-diameter double-guarded calorimeter to determine the performance of the liquid-hydrogen-tank insulation system during simulated prelaunch, launch-ascent, and on-orbit conditions.

Figures 22 and 23 give the steady-state thermal performance of the liquid-hydrogen-tank insulation system for various radiation shield (test chamber) pressures.¹ Pressures within the foam, near the tank surface, were also recorded and were roughly 10 times higher than the chamber pressure. The test configuration shown (i.e., with two polyimide foam layers) was actually an earlier version of the forward bulkhead insulation, and the tests were primarily designed to simulate the helium-purged forward adapter area of the vehicle. The data, however, should be representative (1) of the single-layer foam configuration (selected for the forward bulkhead) for the lower pressures, where the foam contributes little thermal resistance, and (2) the tank sidewall insulation, provided the volume beneath the inner shield evacuates reasonably well.

¹Data from an internal GDSSD report by A. Burgelis. A limited amount of the data is reported in reference 8.

The temperature data in figure 22 are quite consistent and generally show the expected effects of decreasing pressure. That is, the foam temperatures decreased rapidly, and the radiation shields began to approach a fourth power temperature profile. Most of the data were taken with the thermocouples accidentally unshielded (i.e., the high emissivity epoxy cement used to secure the thermocouples to the shield was left exposed and locally affected the shield temperatures but had no effect on heat transfer). One set of data, however, at a pressure of 2×10^{-4} torr, were taken with the thermocouples properly covered with aluminized tape, and this set varied significantly from the other data. The temperatures acted as expected and in fact approached those of the predicted results for pure radiation heat transfer shown on the left side of the figure.

The heat transfer data shown in figure 23 indicate that, for the lower pressures expected on-orbit (i.e., 10^{-4} torr or less), heat transfer rates on the order of 1 Btu/hr ft² will be achievable with external shield temperatures of 465 °R. The predicted data given in figure 21 show the lowest heating rates and corresponding outer shield temperatures to be about 1.14 Btu/hr ft² and 400 °R for the sidewall and 0.85 Btu/hr ft² and 335 °R for the forward bulkhead. It is obvious that if the experimental data were scaled to the outer shield temperatures expected on-orbit, the heating rates would be even lower than required to accomplish the mission.

One of the concerns was how rapidly the forward bulkhead foam would evacuate in order to quickly achieve the desired lower heat transfer rates on-orbit. Figure 24 indicates that most of the helium gas would be vented quite rapidly. After 5 min the heat transfer rate has dropped to less than 5 Btu/hr ft². The slower dropoff after 5 min was due to a hydrogen leak in the calorimeter. Additional tests were planned to repeat these tests but were abandoned when the shuttle/Centaur program was terminated. It is expected though that heat transfer rates on the order of 1 Btu/hr ft² would be achievable within 15 min after launch.

Tests Related to Shuttle Cargo Bay Safety Requirements

Electrostatic discharge. - One of the requirements for the shuttle cargo bay hardware was that any surface exceeding a volume resistivity of 10^9 ohms-cm be designed to prevent the accumulation of an electrostatic charge. Because the volume resistivity of the Teflon film on all outboard radiation shields exceeded 10^{15} ohms-cm, some means of preventing a charge accumulation had to be provided or, with proper safety verification, a waiver could be obtained. As mentioned earlier, the hidden VDA beneath the Teflon surface was grounded with a conductive ink applied at the shield edges. This grounding technique was selected after trying several mechanical methods of grounding such as rivets, serrated washers, and stainless steel thread. Most of the mechanical methods achieved a good ground initially, but the ground disappeared after a short time probably from galvanic corrosion with the thin VDA layer or from mechanical breakdown of the contact with material flexing. Figure 25 shows the effect of time on the grounding capability of conductive ink for 60 samples each of the Kevlar-reinforced shields on the liquid-hydrogen-tank sidewall and the Nomex-scrim-reinforced shields used on the liquid-oxygen tank. Because some degradation takes place with time, test tabs were designed into the radiation shield system to check the electrical grounding before flight. Many areas existed on the shields (e.g., vent holes in

outer shield) for reapplying the conductive ink in the unlikely possibility that all grounding disappeared.

With the metalized surfaces properly grounded the problem of volume resistivity of the Teflon film still had to be addressed. Two approaches were considered. The first was to consider alternative materials that had lower resistivity, and the second was to examine grounding techniques like that used on the cargo bay liner, where a 6-in.-square grid of grounding wire was interwoven into the beta-cloth liner. In selecting an alternative material both the high strength properties of the sidewall shield material and the desirable optical properties of the VDA-backed Teflon film had to be retained. One possible solution was to add a thin coat of indium tin oxide (ITO) to the Teflon to lower the resistivity at the surface. Discussions with other spacecraft designers and evaluation of material samples revealed that the ITO coating was very brittle and that microscopic cracks in the surface severely degraded its conductive qualities. Because of the extreme flexing of the shields during fabrication, handling, and use on the vehicle, we felt that the ITO coating would be rendered useless and this approach was abandoned.

The use of grounding wires attached to the outer shield surface was also briefly investigated. Experimental measurements of the surface charge on the outer shield material near a grounded wire revealed that the surface charge dropped to near zero at the wire but assumed the full charge fractions of an inch away from the grounding wire. Thus to achieve the desired result, an inordinately large number of grounding wires would be required.

Since neither approach was adequate for achieving the desired low surface resistivity and other methods were not evident, we decided to evaluate the consequences of accumulating a static charge. A series of tests were set up whereby a sample of the shield material was purposely charged to the highest induced potential that was practically possible and then purposely discharged. The charge lost during the discharge was measured. The energy in the arc was then calculated by conservatively assuming that both the maximum measured induced potential and the maximum measured charge lost were doubled once and then again, as an additional factor of safety. This yielded an arc energy of 0.0017 mJ (a factor of 16 higher than that using the measured data). From the data of reference 9 the minimum energy required to sustain a reaction (ignition energy) for the most explosive mixture of hydrogen and air possible is 0.017 to 0.018 mJ. This is 10 times higher than the conservatively calculated arc energy based on experimental measurements.

In addition, if the volume concentration of hydrogen in air varies from the optimum, the required ignition energy can increase dramatically. This fact along with the following was used in achieving a waiver of the resistivity requirement for the outboard shields of the Centaur G-prime:

(1) There is no known charging mechanism during prelaunch, ascent, and abort descent.

(2) All metalized surfaces were grounded, including the hidden VDA.

(3) Any inadvertently applied charge (e.g., rubbing against surface by personnel) would bleed off well before the tanks were loaded with cryogenics.

(4) Built-in clearance between the radiation shields and the cargo bay precluded inadvertent contact with a grounded surface.

Flow impingement from cargo bay vents. - One of the concerns that arose in integrating the Centaur into the shuttle cargo bay was the effect of high-velocity flow near the open cargo bay vents during shuttle ascent and descent. Because of the large diameter of the Centaur G-prime, the liquid-hydrogen-tank sidewall insulation system was relatively close to two of these open vents, and there was concern that the high-velocity flow could cause flutter or damage to the overlying radiation shields. Since it was not possible to predict the flutter- or flow-induced oscillatory stresses, a test was set up to determine the shields' responses to these conditions.

A preliminary worst-case assessment of the airflows, by the STS prime contractor, gave estimates of the velocity and dynamic pressure q for various flight events at the two open vents exposed directly to the sidewall insulation system. The worst-case events are summarized in table V along with the experimental airflows (at sea level) used to simulate these events. For the ascent condition, where the shield would be unpressurized, the maximum test airflow velocity was selected to be the same as the maximum predicted in flight. The corresponding q was 52 lb/ft^2 , or 1.58 times the predicted 33 lb/ft^2 during flight. The descent events with the shield pressurized would generally be more severe in terms of velocity and dynamic pressure. The test condition selected applied a safety factor of 1.4 to the event with the maximum dynamic pressure (130 lb/ft^2), yielding a test q of 182 lb/ft^2 . Although the test velocity was only 391 ft/sec, it exceeded the estimated velocity of 209 ft/sec required to match the Reynolds number of the flight event. The flight event that could not be matched was the high velocity inflow at the higher altitudes (i.e., 1420 ft/sec at 72 500 ft). This event is not considered critical, however, because of the relatively low dynamic pressure. In addition, later detailed estimates indicated that the velocity at this altitude would be closer to 840 ft/sec, which further lowers the dynamic pressure to about 14 lb/ft^2 .

The experimental test setup and flow profiles imposed on a sample shield to simulate the events discussed are shown in figure 26. The shield sample, the simulated vent area, and the distance between the vent and the shield surface were to the same scale as the flight hardware. The foam beneath the shield also contained a row of twin-pin fasteners (not shown) near the flow impingement area to magnify any deleterious abrasion effects in case flutter occurred. The test flow rates shown were slowly ramped to the maximum test dynamic pressures to determine if there were any oscillatory phenomena that only occurred at the lower flow rates. With the shield unpressurized some limited movement was observed, but the movement was not organized and was of very small amplitude. During testing of the pressurized shield very little movement was noted. There was no damage to the radiation shield or the foam beneath the shield (fig. 27).

Early in the test program a flow control valve accidentally malfunctioned and exposed an unpressurized shield to a dynamic pressure of at least 1800 lb/ft^2 . The shields and foam experienced some damage, but because it was very localized, the shield system could still contain a helium purge. The middle shield, which was the lightweight embossed Kapton material, partially shredded near the flow impact area. We believe that the high-pressure air entered through the vent holes in the outer shield (0.25-in.-diameter holes on

4-in. centers) and caused the thinner (0.3 mil) Kapton material to shred locally. Although these conditions would never occur during flight, we decided as a precautionary measure to tape over the shield vent holes near the cargo bay vents to prevent any possible degradation due to flow impingement.

Liquid air formation. - During an abort of the shuttle after lift-off the liquid-hydrogen-tank insulation system helium purge would have to be reinitiated for an eventual descent and landing. Although the Centaur propellant tanks would be emptied in the event of an abort, some residual propellants would remain in the cold-soaked tanks. If for some reason the helium purge was unexpectedly terminated or was not reinitiated, air could be ingested into the sidewall insulation system and eventually condense on the cold liquid-hydrogen-tank surface. One of the concerns for this failure scenario was that liquid air (1) could possibly compromise the structural integrity of the radiation shields or (2) could form on the external surfaces of the sidewall radiation shields and present a potential hazard to the shuttle and its crew. Conservative estimates indicate that roughly 40 lb of liquid air could be generated in vaporizing the remaining residual liquid hydrogen and warming the tank above the condensation temperature of air. If it was further assumed that all the liquid would collect on the inner shield (vehicle in horizontal position), the inner shield temperature could drop low enough to condense the surrounding external air.

As a result of these concerns a small-scale experiment was set up to demonstrate the liquid-air containment capabilities of the sidewall radiation shields. The overall experimental setup is shown in figure 28. A sample of the three-layer sidewall shield was used to form the major surface of a dish-shaped container that was then filled with liquid nitrogen. A typical sewn seam ran longitudinally along the bottom of the dish and was instrumented with thermocouples on the underside (not shown) to help determine if liquid-air temperatures were approached. Liquid nitrogen was used because it represented the coldest temperature achievable with liquid air condensing inside the radiation shield system. The dish held approximately 110 lb of liquid nitrogen when filled. The resulting temperature profile across the shield seam is shown in figure 29. It is apparent that all the temperatures are relatively high, probably as a result of water frost buildup between the shield layers. There was no evidence of structural degradation of the shield seam and no evidence of liquid runoff during the entire test. After the primary testing was completed, a small propane torch was passed back and forth below the shields (~10 in.) to detect any liquid air or concentrations of gaseous oxygen that were not detectable from the visual observations. There were none.

On the basis of the tests conducted and the sidewall shield design used, we concluded (1) that any air ingested and subsequently liquefied within the liquid-hydrogen-tank insulation system would be contained by the inner (sealed membrane) radiation shield; and (2) that there would be no external formation of liquid air on the radiation shield system.

Impact sensitivity of materials in liquid air/gaseous oxygen. - Because there was a potential of forming liquid air within the liquid-hydrogen-tank insulation system after single-point failures causing loss or depletion of the helium purge during an abort, it became necessary to prove (1) that the insulation system was not impact sensitive in a liquid-air or a gaseous-oxygen environment or (2) that the probability of catastrophic failure due to impact was

extremely low. Tests to accomplish this were under way when the shuttle/Centaur G-prime program was terminated. Partial results from one series of tests are summarized in table VI. The objective of these tests was to determine the impact sensitivity of the insulation materials in gaseous oxygen. The reason for this was that if any impact on the vehicle occurred, there would be a considerably higher probability of the insulation behind the impact area being flooded with gaseous oxygen rather than the liquid air, which would be in a small puddle. As seen from table VI the test results were mixed. A material has to be capable of sustaining 20 successive impacts at 72 ft-lb without a reaction before it is considered not to be impact sensitive. The inner shield material, which is the only shield exposed to gaseous oxygen, passed the test. The three-layer sidewall shield with a typical taped seam and the polyimide foam, however, could only pass at the lower energy levels. The pressures used in the tests were considerably higher than desired because of the limitations of the standard test equipment. Plans were under way to modify the equipment for gaseous oxygen tests at 1 atmosphere but could not be completed. From the limited data taken at 50 psia, it appeared that there was a good possibility that the materials would have passed the impact testing at pressures near ambient. For example, the polyimide foam, which could not pass the impact tests in gaseous oxygen at 50 psia, did pass the liquid-oxygen impact tests that were done at a pressure of 1 atmosphere.

It should be noted, however, that the polyimide foam was the only element of the sidewall insulation system that passed the standard ambient liquid-oxygen impact test of reference 7. This particular test completely immerses a small wafer of the candidate material in a stainless steel cup filled with liquid oxygen and then impacts it with a stainless steel anvil. In the failure scenarios discussed previously, only the materials inboard of the innermost sidewall radiation shield are exposed to liquid air. Also any impact would be cushioned by the 1.5 in. of foam (which passed the liquid-oxygen impact testing) that separates the shields from the liquid-hydrogen tank. For these reasons an experiment was devised to determine the impact sensitivity of the full insulation system configuration with liquid air contained within the innermost shield only. A sketch of the test setup is shown in figure 30. This test was also in progress when the shuttle/Centaur program was canceled.

Both the partially completed impact testing discussed above and tests on the external formation of liquid air (previous section) were an attempt to realistically assess the potential hazards involved with ingesting air into the liquid-hydrogen-tank insulation system after a single-point failure causing loss of helium purge. The assumptions used in estimating the amount of liquid air that would form and remain as a liquid were very conservative but justifiably so when the safety of the shuttle and its crew were involved. Depending upon the results of the uncompleted impact testing the insulation system may have demonstrated a benignity to impact and hence met the two-failure tolerancy requirement. If not, steps would have been taken to add another level of redundancy to events causing loss of helium purge.

Full-Scale Insulation System Tests

A full-scale test of the liquid-hydrogen-tank insulation system was conducted: (1) to determine the performance characteristics of the helium purge system, (2) to determine the thermal characteristics and performance of the

insulation system, and (3) to evaluate the structural integrity of the insulation system. The test vehicle consisted of the Centaur G-prime propellant tanks, the forward and aft composite adapters, and the forward adapter with the purge diaphragm. Figure 31 shows the vehicle before it was installed in the test tower and before the liquid-hydrogen-tank sidewall insulation system was installed. Once in the test tower the vehicle was enclosed in a shroud that was subsequently purged with gaseous nitrogen during testing to simulate the shuttle cargo bay during prelaunch. Liquid nitrogen rather than liquid oxygen was used in the uninsulated liquid-oxygen tank for safety reasons.

The insulation system on the liquid-hydrogen tank consisted of the flight design with some minor variations to accommodate the various full-scale vehicle tests planned. Also as mentioned earlier the radiation shield material originally selected and used for these tests was the fiberglass-cloth-reinforced shield material whose strength properties are given in table III.

Purge system tests. - The results of key tests on the blanket purge system are given in figures 32 and 33. The measured helium leakage rate of the insulation blanket system (fig. 32) was well within the target leakage and showed no significant hysteresis effects. The results of two gaseous nitrogen displacement tests (fig. 33) show the gaseous nitrogen concentration as a function of time for two different gaseous helium flow rates. The higher rate was selected and used for the Centaur G-prime insulation system. As mentioned in the discussion of figure 6 the gaseous-nitrogen removal cycle is initiated by pressurizing the blanket with helium until the two relief valves open to allow a flow path for removing the heavier gaseous nitrogen. It is apparent that the hour allowed for this cycle is sufficient for removing most of the gaseous nitrogen from the system. The two relief valves, which were designed to open between 0.35 and 0.45 psid, opened at 0.403 and 0.405 psid, respectively.

The control system for supplying the helium to the blanket performed flawlessly. Typical pressure histories for the blanket purge system are given subsequently in the section "Flight Vehicle Ground-Hold Testing."

Thermal performance tests. - A summary of the thermal data taken on the insulated liquid-hydrogen tank during simulated prelaunch conditions is shown in figure 34. The outer and inner radiation shield temperatures and outer foam surface temperature data are shown as a function of the liquid-hydrogen-tank vertical and radial positions. Also included for reference is the predicted temperature of the inner and outer shields. The agreement between predicted and measured shield temperatures was quite good except for the aft (conical) end of the liquid-hydrogen tank. The measured temperatures on the aft end of the conical shield are markedly lower than expected. Although the temperatures were not low enough to cause liquid-nitrogen runoff, they were low enough to form water frost from the small amount of residual moisture left in the gaseous-nitrogen purge (dewpoint of -30 °F). After careful post-test inspection, we concluded that the seams in the foam, where butt joints of the inner and outer foam layers coincided, were allowing the cold helium next to the liquid-hydrogen-tank wall to flow directly out to the inner shield, causing localized chilling. All of these overlying butt joints were concentrated in the cableway area, where the electrical wires and fluid lines ran up the sidewall (~90° position) and around the major tank penetrations such as the fill/drain line and the engine feed line elbows (e.g., see fig. 16). The measured shield temperatures were correspondingly lowest in this region (i.e., at the 45° and 135° positions). As a result of these tests the design was changed to

include local taping of the butt joints around the areas discussed. Subsequent testing of the full-scale flight vehicle confirmed that no localized chilling occurred.

The measured heat transfer rate of 82 700 Btu/hr into the liquid-hydrogen tank was well within the maximum and minimum rates of 76 857 and 86 935 Btu/hr predicted for the test article. These rates differed slightly from those of table II because of the various peculiarities associated with the test (e.g., using liquid nitrogen rather than liquid oxygen in the liquid-oxygen tank and different tank penetrations on the forward end). Overall, the thermal performance of the system was as expected.

Structural tests. - At the conclusion of the purge and thermal performance testing several structural tests were performed on the helium containment shield (innermost shield). The first test consisted of a rapid pressurization to simulate the maximum rate of pressure change expected on the insulation system during shuttle ascent - about 0.3 psid/sec. The second test attempted to impose a proof pressure of 0.5 psid on the system, and the final test pressurized the shield until it failed (burst test). Prior to these tests extensive crazing or localized creasing of the outer shield material was evident (also expected on the inner containment shield), and four small tears in the outer shield occurred as a result of the nitrogen purge gas removal tests. Despite these tears the blanket leakage remained unchanged, indicating no failure in the inner containment shield. These tears were repaired before the subsequent structural tests were performed. The shield system withstood the rapid pressurization tests with no change in blanket leakage although another small tear appeared. In the proof pressure test a pressure of 0.57 psid rather than 0.5 psid was applied because of an instrumentation problem. Several additional tears in the outer shield appeared and the blanket leakage increased. In the subsequent burst test the blanket failed at 0.66 psid, well above the design proof pressure.

As mentioned previously the shield material selected for the flight vehicle was the stronger Kevlar-cloth-reinforced material. The actual decision to change materials occurred before the structural tests when extensive creasing appeared after the fiberglass-reinforced shields had been installed for the full-scale vehicle tests. The results of the structural tests further reinforced this decision.

Flight Vehicle Ground-Hold Tests

The first flight vehicle and its CISS were mounted in a simulated cargo bay at Cape Kennedy for a terminal countdown demonstration (TCD). In this test the vehicle was tanked and controlled by its onboard computer systems up to a simulated abort just prior to lift-off. Two TCD's were performed. The thermal performance of the insulated propellant tanks for the second TCD is summarized in figure 35 (results similar to that of the first TCD). The steady-state temperatures of the insulation system are shown for the various flight temperature transducers used on the vehicle. For reference the temperature data acquired on the full-scale developmental tests (previous section) are included where the sensors are in the same general location. In the forward bulkhead area the lower temperatures measured for the flight vehicle were expected since the shields on the developmental test vehicle were more loosely fitting. The original design of the developmental vehicle had two layers of foam on the forward

bulkhead but was ultimately tested with one layer, hence causing the looseness in the shields.

The sidewall temperatures on the flight vehicle were higher, and the spread between the inner and outer shields was also higher, indicating more heat was supplied (from the surrounding walls) to the outer shield. This was expected since the emittance of the simulated cargo bay used for the TCD was considerably higher than that used for the developmental testing, where costs were kept low by using a bare oxidized aluminum material for the shroud sidewalls. The simulated cargo bay emittance was 0.85, whereas the simplified shroud used for the developmental testing had an estimated emittance of about 0.15. We estimated that this would cause a roughly 10 to 15 percent increase in the sidewall heating for the TCD test, and this was reflected in the test results.

Note also that the temperatures on the conical portion of the flight sidewall shield were considerably higher and more uniform radially than those experienced on the developmental test article (fig. 34), indicating that the localized chilling experienced previously did not occur.

The steady-state heat transfer rates for the liquid-hydrogen and -oxygen tanks as determined from boiloff tests were 88 500 and 44 000 Btu/hr, respectively.

The liquid-hydrogen-tank insulation blanket purge system performed flawlessly throughout the simulated prelaunch countdown. Figure 36 shows a typical pressure history of the blanket demonstrating the cycling of the blanket at 5 min before the planned launch. Prior to T - 5 min the blanket was in its nominal cycle mode. At T - 5 min the control band was changed via software to prepare for the events at lift-off. The control band was tightened so that the peak differential pressure was low enough to ensure that the blanket ΔP would not exceed 0.35 psid when the cargo bay vents were opened at T - 41 sec. The average ΔP of the blanket was also raised in preparation for terminating the purge at T - 20 sec. This blanket differential pressure ensures that the ΔP would still be positive at lift-off and prevents any backfilling with air. It is apparent from figure 36 that the overall cyclic performance of the blanket was smooth and well behaved.

Post-test inspection of the insulation systems after the two TCD's indicated that no structural damage occurred. There was no evidence of tears in the liquid-hydrogen-tank shields as experienced in the developmental tests and no evidence of shield creasing.

CONCLUDING REMARKS

Overall, the Centaur G-prime cryogenic thermal protection systems, as designed and modified subsequent to the full-scale development tests, met all structural and thermal requirements for the intended G-prime missions. The liquid-hydrogen-tank thermal protection system was the focus of most of the developmental efforts because its design had the additional requirement of preventing the formation of liquid nitrogen or air on any of its surfaces to prevent potential hazardous situations in the shuttle cargo bay.

The helium-purged foam and radiation shield blanket concept for the liquid-hydrogen tank proved to be lightweight, rugged, and reliable. The high-strength Kevlar-cloth-reinforced shields were more than adequate for withstanding all the pressure loads imposed on the system during prelaunch, launch, and ascent (including flow impingement through cargo bay vents) and during abort. The measured thermal performance of the liquid-hydrogen-tank insulation system during simulated prelaunch conditions was essentially as predicted, and limited calorimeter data indicated that the thermal performance on-orbit would have been adequate for the intended missions. The helium purge system for maintaining a helium environment around the liquid-hydrogen tank during all operations within the atmosphere performed flawlessly.

A considerable amount of development effort was necessarily devoted to safety issues. The basic thermal protection system materials had to, and did, meet strict cargo bay flammability, cleanliness, and outgassing requirements. The basic system design exceeded the structural design requirements for cargo bay payloads. In fact, the initial design, using the degraded fiberglass-cloth-reinforced shields, nearly met all structural requirements. The much stronger Kevlar-cloth-reinforced shields that were finally selected clearly exceeded the requirements and showed no structural degradation after extensive testing during the terminal countdown demonstrations. The requirement to properly ground (electrically) all metalized surfaces was met. Grounding of the "hidden" vapor-deposited aluminum (VDA) in the outermost radiation shield was especially challenging. It was accomplished by applying conductive ink to the shield edges to electrically join the hidden VDA with the exposed VDA on the underside of the outer shield.

Finally, the most difficult task involved demonstrating that the insulated liquid-hydrogen tank would be safe if the helium purge was lost during a abort. Two functions critical to providing helium during an abort and descent were (1) the closure of the abort vent door in the forward adapter to allow repressurization of the insulation blanket with helium and (2) the operation of the helium purge supply. Although, many of the elements of both systems were two-failure tolerant (e.g., dual pyrotechnics for the vent door pin puller, three AP transducers, and redundant software), there were remote situations where a single failure could cause loss of helium purge. These functions could have been made two-failure tolerant but not without additional weight and complexity. Therefore a considerable effort was spent looking at the effects of ingesting air into the liquid-hydrogen-tank insulation system. Tests demonstrated that no liquid nitrogen or liquid air would form on the outside of the shields even if colder liquid nitrogen was contained within the inner shield. So even with a failure of the purge supply to the insulation, the shuttle could land without the hazard of the cargo bay being exposed to liquid nitrogen or liquid air.

However, since there was a possibility of having liquid air within the insulation blanket after a single failure, it had to be demonstrated that the system was benign to possible impacts. Efforts were under way to demonstrate the impact sensitivity of the insulation system with low-pressure (1 atm) liquid air or gaseous oxygen contained in the system when the shuttle/Centaur program was canceled. The preliminary test results taken at a pressure of 50 psia were mixed but looked promising. We felt that there was a good possibility of the system being benign to impacts when tested as a system at atmospheric pressures. If not, additional redundancy would have been required for the helium purge system.

In summary, the combined helium-purged foam and radiation shield system used for the Centaur G-prime liquid-hydrogen tank proved to be an effective lightweight method of providing thermal protection during both ground-hold and on-orbit operations. The technology and information generated under this developmental effort should be directly applicable to the design of cryogenic thermal protection systems for future shuttle or upper stage applications.

REFERENCES

1. Spurlock, O.F., "Shuttle/Centaur - More Capability for the 1980's," IAF Paper 83-18, Oct. 1983.
2. "Atlas-Centaur AC-19 and AC-20 Performance for the 1969 Mariner Mars Missions," NASA TM X-2278, 1971.
3. Lacovic, R.F., "Thermodynamic Data Report for the Titan/Centaur TC-5 Extended Mission," NASA TM X-73605, 1977.
4. "Safety Policy and Requirements for Payloads Using the Space Transportation System (STS)," NASA TM-85402, 1982. (NHB-1700.7A.)
5. "Payload Ground Safety Handbook," KHB-1700.7, Rev. A.
6. "Shuttle System Requirements for Shuttle Centaur Stage and Airborne Support Equipment," NASA Johnson Space Center, JCS-07700, Vol. X, Appendix 10.16, Dec. 1985.
7. "Flammability, Odor, and Outgassing Requirements and Test Procedures for Materials in Environments That Support Combustion," NASA TM-84066, 1981. (NHB-8060.1B.)
8. Pleasant, R.L., "Heat-Transfer Through Liquid-Hydrogen Tank Insulation on Shuttle/Centaur G-Prime," Cryogenic Properties, Processes and Applications 1986, A.J. Kidnay and M.J. Hiza, eds., AIChE, New York, 1986, pp. 75-80. (AIChE Symposium Series, Vol. 82, No. 251.)
9. Magison, E.C., Electrical Instruments in Hazardous Locations, Third Revised Edition, Instrument Society of America, Pittsburgh, 1978.

TABLE I. - RADIATION-SHIELD DETAILS FOR G-PRIME LIQUID-HYDROGEN TANK

| Basic shield material | Outboard surface material | Inboard surface material | Area of use | Unit weight, lb/ft ² |
|-----------------------|---------------------------|--------------------------|---|---------------------------------|
| Embossed Kapton | VDA ^a | VDA | Middle (center) shield on purge diaphragm, forward bulkhead shields, and sidewall shields | 0.0022 |
| Kapton sheet | VDA | VDA | Inboard shield on forward bulkhead | .0022 |
| Kevlar cloth laminate | VDA-Kapton (0.5 mil) | Kapton-VDA (0.5 mil) | Outboard and inboard shields of purge diaphragm and inboard shield on sidewall | .04 |
| Kevlar cloth laminate | Teflon-VDA (0.5 mil) | Kapton-VDA (0.5 mil) | Outboard shield of liquid-hydrogen-tank sidewall | .04 |
| Nomex scrim laminate | VDA-Kapton (0.3 mil) | Kapton-VDA (0.3 mil) | Outboard shield on forward bulkhead | .02 |

^aVapor-deposited aluminum.TABLE II. - SHUTTLE/CENTAUR G-PRIME LIQUID-HYDROGEN-TANK STEADY-STATE HEATING DURING PRELAUNCH OPERATIONS AND DURING ON-ORBIT PORTION OF GALILEO MISSION (OPEN DOOR, PREDEPLOYMENT^a)

| | Prelaunch ^b | | On-orbit | | |
|-----------------------|------------------------|---------|----------|---------|---------|
| | Maximum | Minimum | Maximum | Nominal | Minimum |
| | Heating rate, Btu/hr | | | | |
| Forward bulkhead | 20 600 | 19 600 | 202 | 184 | 165 |
| Forward adapter | 7 500 | 5 700 | 121 | 110 | 99 |
| Sidewall | 49 970 | 45 000 | 671 | 610 | 549 |
| Penetrations | 4 085 | 4 085 | 407 | 370 | 333 |
| Intermediate bulkhead | 1 835 | 1 115 | 1835 | 1475 | 1115 |
| Gaseous-helium purge | 4 445 | 2 440 | --- | --- | --- |
| Total | 88 435 | 77 940 | 3221 | 2735 | 2249 |

^apayload doors open with orbiter tail oriented to Earth.^bCargo bay gaseous-nitrogen inlet temperature of 55 °F at flow rate of 180 lb/min past liquid-hydrogen-tank sidewall.

TABLE III. - STRUCTURAL TEST RESULTS ON SIDEWALL SHIELD MATERIALS AND SEWN JOINTS

(a) Basic material tests

| Laminate | Tensile strength, ^a lb/in. | Tensile strength ^a (creased), lb/in. | Modulus, E, lb/in. |
|------------|---------------------------------------|---|--------------------|
| Fiberglass | 154 | 33 | 3173 |
| Kevlar | 239 | 191 | 7767 |

(b) Pull tests on sewn seams

| Type of seam | Description | Tensile strength ^a (at failure), lb/in. |
|---|--|--|
| Overlap with two rows of stitching (Kevlar) | Shield sewn to shield: Warp direction Fill direction Shield to edge member (warp direction) | 231 213 302 |

^aDesign requires 43.5 lb/in. at $\Delta P = 0.5$ psid.

TABLE IV. - SHUTTLE/CENTAUR G-PRIME RADIATION SHIELD SURFACE
PROPERTY REQUIREMENTS AND MEASUREMENTS

| Outer surface material | Specification values | | Averaged measured values ^a | |
|--|-------------------------|-------------------------|---------------------------------------|---------------------|
| | Thermal emittance | Solar absorptance | Thermal emittance | Solar absorptance |
| Shields | | | | |
| Teflon-VDA VDA-Kapton Fiberglass | >0.40 ≤ .05 ≥ .81 | <0.14 ≤ .14 ≤ .35 | 0.44 .04 .88 | 0.132 .09 .31 |
| Tapes | | | | |
| Teflon-VDA Aluminized Kapton | >0.40 ≤ .05 | <0.14 ≤ .14 | 0.46 .043 | 0.12 .134 |

^aMeasurements were made using a Lion Research Corp. reflectometer/emissometer model E25B.

TABLE V. - CARGO BAY VENT FLOW RATES AND TEST FLOW RATES FOR VARIOUS SHUTTLE FLIGHT EVENTS

| Cargo bay vent | Flight ^a | | | | | | Test inflow at sea level | | |
|----------------|---------------------|----------------|--------------------|---------------------|---|-------------------------|--------------------------|---|-------------------------|
| | Phase | Flow direction | Altitude, ft | Velocity, V, ft/sec | Dynamic pressure, q, 1b/ft ² | Insulation pressurized? | Velocity, V, ft/sec | Dynamic pressure, q, 1b/ft ² | Insulation pressurized? |
| 6 | Ascent | Out | 20x10 ³ | 130 | 11 | No | 130 | 20 | No |
| 5 | Ascent | In | 14 | 210 | 33 | No | 210 | 52 | No |
| 6 | Descent | Out | 30 | 90 | 2 | Yes | 391 | 182 | Yes |
| 6 | In | 72.5 | 1420 | 40 | | | --- | --- | --- |
| 5 | In | 72.5 | 970 | 18 | | | --- | --- | --- |
| 5 | In | 28 | 550 | 130 | | | 391 | b182 | Yes |

^aRockwell International data presented at Centaur G-prime design review.

bSafety factor of 1.4 applied to flight q of 130 lb/ft².

TABLE VI. - IMPACT SENSITIVITY OF LIQUID-HYDROGEN-TANK SIDEWALL INSULATION SYSTEM MATERIALS IN LOW-PRESSURE GASEOUS OXYGEN

[Test medium, 100 percent gaseous oxygen; test pressure, 50 psia.
See ref. 7 for a description of the test procedures.]

| Material | WS1Fa test report | Impact energy, ft-lb | Number of reactions | Number of tests |
|---|-------------------|--|--|----------------------------------|
| Polyimide foam | 86-20077 | 72 65 60 55 50 45 40 35 30 25 20 | 2 1 1 1 1 1 1 1 1 0 | 2 1 1 2 1 8 20 |
| Inner shield material (Kevlar cloth laminate) | 85-20076 | 72 | 0 | 20 |
| Taped seam from three-layer sidewall shield | 86-20078 | 72 65 60 55 40 30 25 20 15 | 2 1 1 1 1 1 1 1 0 | 3 1 5 19 2 20 |

^aJohnson Space Center White Sands Test Facility.



FIGURE 1. - SEPARATION OF SHUTTLE/CENTAUR G-PRIME FROM SHUTTLE VEHICLE IN ORBIT.




FIGURE 2. - SHUTTLE/CENTAUR G-PRIME CONFIGURATION AND MAJOR STRUCTURAL INTERFACES.

ORIGINAL PAGE IS
OF POOR QUALITY




FIGURE 3. - BASIC SHUTTLE/CENTAUR G-PRIME VEHICLE CONFIGURATION (BEFORE INSTALLATION OF THERMAL PROTECTION SYSTEMS AND FLIGHT HARDWARE).




FIGURE 4. - SHUTTLE/CENTAUR G-PRIME THERMAL PROTECTION SYSTEMS.




FIGURE 5. - AFT-END THERMAL PROTECTION OF SHUTTLE/CENTAUR G-PRIME VEHICLE.




FIGURE 6. - INSULATION BLANKET PURGE SYSTEM OPERATION FOR SHUTTLE/CENTAUR G-PRIME LIQUID-HYDROGEN TANK.




FIGURE 7. - PRIMARY THERMAL PROTECTION SYSTEMS USED ON SHUTTLE/CENTAUR G-PRIME LIQUID-HYDROGEN TANK.




FIGURE 8. - GENERAL CONSTRUCTION OF SHUTTLE/CENTAUR G-PRIME PURGE DIAPHRAGM. (SECTIONS ARE NOT TO SCALE.)




FIGURE 9. - INSTALLED PURGE DIAPHRAGM ON FULL-SCALE SHUTTLE/CENTAUR G-PRIME TEST VEHICLE.




FIGURE 10. - INSULATION DETAILS ON FORWARD END OF SHUTTLE/CENTAUR G-PRIME LIQUID-HYDROGEN TANK. (POLYIMIDE FOAM USED THROUGHOUT.)

ORIGINAL PAGE IS
OF POOR QUALITY






FIGURE 11. - LAYUP OF POLYIMIDE FOAM FOR FORWARD BULKHEAD OF SHUTTLE/CENTAUR G-
PRIME TEST TANK.



STEP 1



STEP 2




STEP 3


SECTION A-A: TYPICAL SEAM CONSTRUCTION



SECTION C-C: TYPICAL EDGE TREATMENT FOR GORE SECTORS



VIEW B



SECTION D-D



QUADRANTS OVERLAPPED
AND HELD BY TWIN-PIN
FASTENERS ALONG FOUR
FOAM SEAMSVIEW B
TYPICAL CUTOUT
VELCRO
VELCRO PILE FOR ATTACHMENT
TO FORWARD ADAPTER
SHIELD GORE SECTION
STRAIGHT SHIELD SECTION
VELCRO PILE FOR ATTACHMENT
TO FORWARD ADAPTER

FIGURE 12. - GENERAL CONSTRUCTION OF SHUTTLE/CENTAUR G-PRIME FORWARD BULKHEAD RADIATION SHIELDS. (ONLY TWO QUADRANTS SHOWN FOR BREVITY. SECTIONS ARE NOT TO SCALE.)

ORIGINAL PAGE IS
OF POOR QUALITY




FIGURE 13. - DETAILS OF POLYIMIDE FOAM ATTACHMENT FOR SHUTTLE/CENTAUR G-PRIME LIQUID-HYDROGEN TANK.




FIGURE 14. - ATTACHMENT OF POLYIMIDE FOAM PANELS AT FORWARD RING OF SHUTTLE/CENTAUR G-PRIME LIQUID-HYDROGEN TANK.




FIGURE 15. - AFT END OF SHUTTLE/CENTAUR LIQUID-HYDROGEN TANK SHOWING PURGE PLENUM AND BRACKETS FOR FOAM ATTACHMENT.




FIGURE 16. - AFT END OF CABLEWAY AREA.

ORIGINAL DESIGN
OF POOR QUALITY




FIGURE 17. - GENERAL DETAILS OF SHUTTLE/CENTAUR G-PRIME LIQUID-HYDROGEN-TANK SIDEWALL SHIELD CONSTRUCTION.
(SECTIONS ARE NOT TO SCALE.)




FIGURE 18. - SHUTTLE/CENTAUR G-PRIME MATED TO CISS.




FIGURE 19. - TYPICAL ELECTRICAL BONDING TECHNIQUES FOR RADIATION SHIELDS.




FIGURE 20. - GROUNDING OF HIDDEN VDA ON ALL OUTBOARD SHIELDS OF SHUTTLE/CENTAUR G-PRIME.




FIGURE 21. - SHUTTLE/CENTAUR G-PRIME LIQUID-HYDROGEN-TANK SIDEWALL AND FORWARD-BULKHEAD TEMPERATURE AND TANK HEATING PREDICTIONS FROM COMPLETION OF LIQUID-HYDROGEN TANKING TO STEADY-STATE, ON-ORBIT (+XLV, $\beta = 60^\circ$) CONDITIONS.




FIGURE 22. - CALORIMETER TESTS ON CENTAUR G-PRIME LIQUID-HYDROGEN-TANK INSULATION SYSTEM (SYSTEM TEMPERATURES).




FIGURE 23. - CALORIMETER TESTS ON CENTAUR G-PRIME LIQUID-HYDROGEN-TANK INSULATION SYSTEM (HEAT TRANSFER).




FIGURE 24. - INSULATION SYSTEM HEAT TRANSFER RATES DURING SHUTTLE/CENTAUR G-PRIME ASCENT PRESSURE PROFILE.





FIGURE 25. - EFFECT OF TIME ON ELECTRICAL GROUNDING OF HIDDEN VDA IN SHUTTLE/CENTAUR G-PRIME OUTERMOST SHIELDS. (SIXTY SAMPLES OF EACH MATERIAL WERE TESTED.)



(A) TEST SETUP.




FIGURE 26. - TEST SETUP AND FLOW PROFILE USED TO SIMULATE SHUTTLE CARGO BAY VENT INFLOW ON SIDEWALL RADIATION SHIELD.




FIGURE 27. SHUTTLE/CENTAUR G-PRIME SIDEWALL RADIATION SHIELD AFTER EXPOSURE TO SIMULATED FLOW IMPINGEMENT FROM ORBITER VENTS.




FIGURE 28. - TEST SETUP FOR DETERMINING IF LIQUID AIR COULD FORM ON EXTERNAL SURFACES OF SHUTTLE/CENTAUR G-PRIME SIDEWALL RADIATION SHIELD.




FIGURE 29. - EXTERNAL SHIELD TEMPERATURES NEAR SHUTTLE/CENTAUR G-PRIME SHIELD SEAM WITH INNER SHIELD (CONTAINMENT MEMBRANE) IMMersed IN LIQUID NITROGEN.




FIGURE 30. - TEST SETUP FOR IMPACTING SHUTTLE/CENTAUR G-PRIME LIQUID-HYDROGEN-TANK INSULATION SYSTEM WITH LIQUID AIR FORMED INTERNALLY.




FIGURE 32. - EFFECT OF DIFFERENTIAL PRESSURE ON LEAK RATE OF SHUTTLE/CENTAUR G-PRIME LIQUID-HYDROGEN-TANK INSULATION BLANKET.

ORIGINAL PAGE IS
OF POOR QUALITY




FIGURE 31. - CENTAUR G-PRIME TEST TANK BEING INSERTED INTO TEST STAND.




FIGURE 35. - GASEOUS-NITROGEN REMOVAL TESTS ON FULL-SCALE SHUTTLE/CENTAUR G-PRIME LIQUID-HYDROGEN TANK INSULATION SYSTEM.




FIGURE 34. - FULL-SCALE TEST OF SHUTTLE/CENTAUR G-PRIME INSULATED LIQUID-HYDROGEN TANK DURING SIMULATED PRE-LAUNCH. MEASURED HEAT TRANSFER RATE INTO LIQUID-HYDROGEN TANK, 82 700 Btu/hr; NO LIQUID-NITROGEN RUNOFF BUT FROST.




FIGURE 35. - THERMAL PERFORMANCE OF THERMAL PROTECTION SYSTEMS FOR SHUTTLE/CENTAUR G-PRIME FLIGHT VEHICLE 1 CYROGENIC TANKS DURING SIMULATED PRELAUNCH CONDITIONS. HEAT TRANSFER RATES, BTU/HR: INTO LIQUID-HYDROGEN TANK, 88 500; INTO LIQUID-OXYGEN TANK, 44 000.




FIGURE 36. - RESETTING OF BLANKET CONTROL BAND AT 5 MIN BEFORE SIMULATED LAUNCH OF SHUTTLE/CENTAUR G-PRIME FLIGHT VEHICLE 1 (SECOND TANKING).

| | | | |
|--|--|--|-----------------------|
| 1. Report No. NASA TM-89825 | 2. Government Accession No. | 3. Recipient's Catalog No. | |
| 4. Title and Subtitle Design, Development, and Test of Shuttle/Centaur G-Prime Cryogenic Tankage Thermal Protection Systems | | 5. Report Date May 1987 | |
| 7. Author(s) Richard H. Knoll, Peter N. MacNeill, and James E. England | | 6. Performing Organization Code 917-60-01 | |
| 9. Performing Organization Name and Address National Aeronautics and Space Administration Lewis Research Center Cleveland, Ohio 44135 | | 8. Performing Organization Report No. E-3473 | |
| 12. Sponsoring Agency Name and Address National Aeronautics and Space Administration Washington, D.C. 20546 | | 10. Work Unit No. | |
| 15. Supplementary Notes A shorter version of this report was presented at the 22nd Thermophysics Conference sponsored by the American Institute of Aeronautics and Astronautics, Honolulu, Hawaii, June 8-10, 1987 (AIAA-87-1557). Richard H. Knoll, NASA Lewis Research Center; Peter N. MacNeil and James E. England, General Dynamics, Space Systems Division, San Diego, California (work performed under NASA contract NAS3-22901). | | 11. Contract or Grant No. | |
| 16. Abstract The thermal protection systems for the shuttle/Centaur would have had to provide fail-safe thermal protection during prelaunch, launch ascent, and on-orbit operations as well as during potential abort, where the shuttle and Centaur would return to Earth. The thermal protection systems selected used a helium-purged polyimide foam beneath three radiation shields for the liquid-hydrogen tank and radiation shields only for the liquid-oxygen tank (three shields on the tank sidewall and four on the aft bulkhead). A double-walled vacuum bulkhead separated the two tanks. The liquid-hydrogen tank had one 0.75-in.-thick layer of foam on the forward bulkhead and two layers on the larger-area sidewall. Full-scale tests of the flight vehicle in a simulated shuttle cargo bay that was purged with gaseous nitrogen gave total prelaunch heating rates of 88 500 Btu/hr and 44 000 Btu/hr for the liquid-hydrogen and -oxygen tanks, respectively. Calorimeter tests on a representative sample of the liquid-hydrogen-tank sidewall thermal protection system indicated that the measured unit heating rate would rapidly decrease from the prelaunch rate of ~100 Btu/hr ft ² to a desired rate of <1.3 Btu/hr ft ² once on-orbit. | | 13. Type of Report and Period Covered Technical Memorandum | |
| 17. Key Words (Suggested by Author(s)) Cryogenics; Thermoprotection; Cryogenic insulation systems | | 18. Distribution Statement Unclassified - unlimited STAR Category 18 | |
| 19. Security Classif. (of this report) Unclassified | 20. Security Classif. (of this page) Unclassified | 21. No. of pages 41 | 22. Price* A03 |

